

use of common household cleaners such as: Fantastik®, Glass Plus®, Formula 409®, Mr. Clean®, and Windex®. If the sheet is not coated on both sides, care should be taken during the cleaning process to prevent cleaners from contacting the uncoated side or edges of the sheet.

### Removing Scratches

Fine scratches can be removed by hand polishing with an acrylic polish or paste wax. Apply polish to a soft cloth and rub. When the scratches have disappeared, remove all residue and polish.

### Static Control

There are a number of commercially available plastic cleaners that provide temporary static reduction. Evonik's line of ACRIFIX™ acrylic cleaners and anti-static polishes can be purchased at [www.acrylite-shop.com](http://www.acrylite-shop.com). For more information on ACRIFIX™ products, visit [www.acrifix.com](http://www.acrifix.com).

Washing the sheet with mild soap and water followed by a thorough rinse with clean water will also remove static charge. When drying the sheet, it is essential that the sheet be lightly blotted with a damp cloth. Rubbing with a dry cloth will generate static charge and could scratch the sheet.

The most effective way to remove static charge from acrylic sheet is to blow deionized air on the sheet surface. Deionized air can be produced by attaching a deionizing air gun (available from SIMCO CO., Inc. +1 800 203-3419) to a compressed air hose. A clean, filtered supply of compressed air must be used. Static charge and dirt or chips will be quickly and easily removed by the deionized air stream. The effects of deionized air are only temporary. Handling may, over time, cause the sheet to pick up additional static charge.

For the location of your nearest authorized ACRYLITE® acrylic sheet distributor, visit [www.acrylite.net](http://www.acrylite.net).

This information and all further technical advice is based on our present knowledge and experience. However, it implies no liability or other legal responsibility on our part, including with regard to existing third party intellectual property rights, especially patent rights. In particular, no warranty, whether express or implied, or guarantee of product properties in the legal sense is intended or implied. We reserve the right to make any changes according to technological progress or further developments. The customer is not released from the obligation to conduct careful inspection and testing of incoming goods. Performance of the product described herein should be verified by testing, which should be carried out only by qualified experts in the sole responsibility of a customer. Reference to trade names used by other companies is neither a recommendation, nor does it imply that similar products could not be used.

Evonik Industries is a worldwide manufacturer of PMMA products sold under the ACRYLITE® trademark in the Americas and under the PLEXIGLAS® trademark in the European, Asian, African and Australian continents. ACRIFIX™ is a trademark of Evonik Cyro LLC.

Fantastik® and Windex® are trademarks of the SC Johnson Company; Glass Plus® is a trademark of Reckitt Benckiser Inc.; Formula 409® is a trademark of The Clorox Company; Mr Clean® is a trademark of Procter & Gamble Co.

©2011 Evonik Cyro LLC. All rights reserved. Printed in USA

For the location of your nearest authorized ACRYLITE® acrylic sheet distributor visit [www.acrylite.net](http://www.acrylite.net).



**Evonik Cyro LLC**  
299 Jefferson Road  
Parsippany, NJ  
07054 US

PHONE +1 800 631-5384  
[www.acrylite.net](http://www.acrylite.net)  
[www.acrylite-shop.com](http://www.acrylite-shop.com)



## Framing with ACRYLITE®

Acrylic glazing for artwork,  
prints, photos & collectibles



ACRYLITE® 

3034B-1011-cyro

# ACRYLITE® acrylic sheet provides clear advantages over glass.

ACRYLITE® offers the beautiful clarity of the finest picture frame glazing at half the weight of glass and many times the impact resistance. It is the preferred material for larger framed art and provides the safety warranted in high traffic areas. It is the ideal glazing material for museums, galleries, and homes.

## Thickness Recommendations

Frame Size	United Inches	Minimum Acrylic Thickness
5" x 7"	24	0.060"
8" x 10"	36	0.060"
11" X 14"	25	0.060"
16" X 20"	36	0.060"
24" X 30"	54	0.098"
24" X 36"	60	0.098"
30" X 36"	66	0.098"
32" X 40"	72	0.118"
36" X 48"	84	0.118"

Acrylic sheet expands and contracts with increases and decreases in temperature and in high humidity conditions. Therefore, extra allowances are necessary for thermal and humidity expansion in the framing system.

The frame design should allow for at least 1/16" of clearance for each 12" of frame length and 1/4" of engagement for each 12" of frame length. In conditions of extreme humidity or temperature, greater allowances may be necessary.

## Working with ACRYLITE®

### Storage

ACRYLITE® acrylic sheet is protected with paper or polyethylene masking on both sides. Sheet should be stored vertically, preferably in a rack where the sheet can be fully supported and can lean at approximately a 10 degree angle.

If acrylic sheet is stacked horizontally, it must not be allowed to sag. Take care to prevent debris or dirt from becoming lodged between the sheet as the weight of the material can force debris through the protective masking and damage the sheet. If various sizes are stacked horizontally, the larger sheet should be at the bottom to avoid an unsupported overhang.

ACRYLITE® sheet should not be stored near radiators or steam pipes, in sunlight or near other heat sources, as excessive heat tends to soften and deform the sheet.

### Preparation of Work Area

It is very important to find a clean, dust free work area. Cover the work table with a soft, clean, lint free felt. When the protective masking is removed from the acrylic sheet, it will generate a static charge on the sheet surface. This charge will attract dirt and lint from other nearby surfaces.

To prevent scratching during handling, leave the protective masking on the sheet as long as possible.

### Scribing and Breaking

This method is useful for quick, straight line cutting of short lengths. Lay the masked sheet on a flat surface and mark the line to be scribed (scored). The paper masking can be marked with almost any writing tool including pencil, ball point pens, and felt tip pens for cutting purposes. Use a straight edge held firmly in place to guide the scribe, knife, or glass cutter along the line. Scribe the sheet several times with firm even pressure along the same line.

Next, position the sheet so that the scribed line is just beyond the edge of the working surface. While holding the sheet firmly in place on the working surface near the scribed line, apply a sharp downward pressure to the end of the sheet overhanging the surface edge. This will cause the sheet to break along the scribed line.

Scribing tools made specifically for acrylic can be purchased from most local plastics distributors and are also available from the Fletcher-Terry Company. These cutters utilize the "scribe and break" principle to cut acrylic sheet. For additional details, call Fletcher-Terry direct at +1 888 883-6165 or visit [www.fletcherterry.com](http://www.fletcherterry.com).

### Removal of Masking

To remove the masking, lift one corner, then pull toward the opposite end of the sheet slowly and evenly. The masking should never be exposed to excessive sunlight or outdoor conditions for extended periods of time.

The removal of old or difficult to remove masking can sometimes be assisted by dampening the masking with aliphatic naphtha, kerosene, or hexane. Afterwards the acrylic should be thoroughly washed with mild soap and water and then rinsed again with clean water to remove any residues. When using these solvents, care should be taken to observe the safe handling procedures recommended by the solvent manufacturer and to protect other framing materials or framed items from possible damage. Avoid use of gasoline and sharp-edged objects such as razor blades.

### Cleaning

Should you need to clean the acrylic sheet, use a clean, damp cleaning cloth, such as the 3M® Scotch-Brite® High Performance Cleaning Cloth. Apply only light pressure, rinse with clean water, and dry by blotting with a damp cloth or chamois.

Dust the picture glazing with a soft, damp cloth or chamois. Dry or gritty cloths may cause surface scratches and create a static electric charge on the surface.

Evonik's line of ACRIFIX™ acrylic cleaners and anti-static polishes can be purchased at [www.acrylite-shop.com](http://www.acrylite-shop.com). For more information on ACRIFIX™ products, visit [www.acrifix.com](http://www.acrifix.com).

Do not use window cleaning sprays, kitchen scouring compounds, or solvents such as acetone, gasoline, or lacquer thinner to clean acrylic.

The exception is ACRYLITE® abrasion resistant acrylic sheet. It's proprietary abrasion resistant coating permits